

## MICON 500 FAULT CODES

<b>CODE</b>	<b>DESCRIPTION</b>
C026	Pulser Fault
C027	Pulser Buffer Overflow Fault
C028	Display Disconnect Fault
C029	EEProm Checksum Is Bad
C030	Excessive Reverse Counts
C031	ATC Probe Open
C032	ATC Probe Short
	<b>MICON 500 C/H ONLY</b>
C051	Excess Flow Fault
C076	Pressure Transducer 1 Out Of Range
C077	Pressure Transducer 2 Out Of Range
C078	Ambient Temperature Probe Fault
C079	Gas Temperature Transducer Out Of Range
C080	Pressure Transducer 1 And 2 Out Of Tolerance
C081	Air Purge Or Pressure Switch Kill
C082	Excess Fill Fault